B.R No . 335 Date:31.08.2013

Inspection report for the Work of : Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

By.Sri.Muniyappa G M
Retd.Executive Engineer

Name of Work: Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

B.R.No 335, 31.08.2013

Estimated Cost 19.50

Bill Amount Rs. 1827756.00

Date of Inspection 06-05-15

Observation and Conclusion

the above said work - Improvements of Drains at bagalagunte Main Road left side in Ward (14) has been done by the concerned AE.

the above said work has been inspected along with concerned AE.

the measurements has been checked by me and it is found satisfactory.

G.M.MUNIYAPPA
B.E.(ELECT),
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಆರ್. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
- 560 073.

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

B.R.NO. 335 Dt 31-8-2013



Indeks

S.S.M. Drain with Cover Slab

Verified

G.M.MUNIYAPPA,
B.E.(ELECT),E.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲನಾ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.